Illinois Commerce Commission Pipeline Safety Field Trip Report

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513					
Exit Meeting Contact: Dallas Jett	Total Man Days: 3					
Pipeline Safety Representative(s): Donald Hankins						
Company Representative to Receive Report: Michael Fuller	Emailed Date:					
Company Representative's Email Address: mfuller2@ameren.com	12/20/2012					

Inspection Summary

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Standard Inspection - Field Audit	Macomb	Donald Hankins	Macomb	3	10/16/2012, 10/17/2012, 10/18/2012	Dallas Jett

Statement of Activities

On the above dates, a field audit was conducted at Ameren Illinois, in Macomb, Illinois, to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590. The audit included a review of company documents regarding the specific code sections as identified on the attached inspection forms.

Staff observed an Ameren crew disconnecting service lines at the following locations:

1029 East Lafauette Street, Rushville, Illinois 606 Market Street, Astoria, Illinois 1002 East Carroll Street, Macomb, Illinois

The first two service lines were steel lines that were cut off about a foot from the gas main and then rethreaded and a steel cap installed onto the old service line. The JULIE dig number for 1029 East Lafauette Street was A002761000 and for 606 Market Street was X002760991.

The other line was plastic and an electro fusion cap was installed on to the old service line that was cut about a foot from the gas main. The caps were 1/2" IPS, Central Plastic Company couplings, ASTM D 2513/F1055, PE 3408-4710, electro fusion caps. The JULIE dig number was A002842022.

Regulator stations were inspected during this audit in Macomb, Illinois.

ISSUE(S) FOUND:

NO ISSUES FOUND.

ISSUE(S) CORRECTED:

NO ISSUES CORRECTED.

NOTICE OF AMENDMENT(S) FOUND:

NO NOAs FOUND.

NOA(S) CORRECTED:

NO NOAs CORRECTED.

NOTICE OF PROBABLE VIOLATION(S) FOUND:

Illinois Commerce Commission Pipeline Safety Field Trip Report

NO NOPVs FOUND.

NOPV(S) CORRECTED:

NO NOPVs CORRECTED.